


Tower-Photo	Work Done i.e	Remarks
	<p>Dignity Tower (D1)</p>	<p>Flat No 1603 T/C Slab casting</p>
	<p>Dignity Tower (D1)</p>	<p>Flat No -1603 Door frame repair work</p>
	<p>Dignity Tower (D1)</p>	<p>Chinaware fixing in d1tower flat no 902</p>
	<p>glory Tower (E2)</p>	<p>Wiring work in flat no 1503 on progress</p>
	<p>Dignity Tower (D1)</p>	<p>Chinaware fixing in d1tower flat no 902</p>
<p>Tower-Photo</p>	<p>Work Done i.e</p>	<p>Remarks</p>

	<p>glory Tower (E2)</p>	<p>Chinaware fixing in flat no 201</p>
<p>Tower-Photo</p>	<p>Work Done i.e</p>	<p>Remarks</p>
	<p>Dignity Tower (D1)</p>	<p>flat no 504 civil repair work</p>
<p>Tower-Photo</p>	<p>Work Done i.e</p>	<p>Remarks</p>
	<p>Dignity Tower (D1)</p>	<p>flat no 504 Bim chiping for Lental fixing</p>