



Tower-Photo	Work Done i.e	Remarks
	<p>Pump room</p>	<p>New wiring work in pump room</p>
	<p>Hounour</p>	<p>Unit no 2,3 kitchen saft RCC cutting for Plumbing work</p>
	<p>Cable Tray Fixing</p>	<p>Cable tray fixing below prime and splendor tower on progress</p>
	<p>Dignity</p>	<p>Paint work flat no 203</p>
<p>Tower-Photo</p>	<p>Work Done i.e</p>	<p>Remarks</p>



Dignity

flat No 604 tile repair

Tower-Photo

Work Done  
i.e

Remarks



Dignity

Wiring work flat no 903