



# Sikka Kimaantra Greens

Progress Report For 01.04.25 to 07.04.25

	Photo	Work Done i.e.
	 A photograph showing two construction workers in high-visibility green vests and yellow hard hats working on a brick foundation in a trench. One worker is kneeling and using a trowel to apply mortar to a brick, while the other stands nearby. The trench is filled with red bricks and some concrete blocks. A red car is parked in the background, and there are stacks of lumber and a blue tarp on the ground.	
	 A photograph showing two construction workers in high-visibility vests and hard hats laying out a large quantity of red bricks on a prepared ground surface. The bricks are arranged in neat rows. There are bags of cement and other construction materials scattered around. The background shows a paved area and some trees.	Any Other Work

NTA





Tower Name

Tower Photo



Work Done i.e.



Club

Any Other Work



Tower Name	Tower Photo	Work Done i.e.
Tower Name	Tower Photo	Work Done i.e.
	 A photograph showing several tall, modern apartment towers under construction. The buildings are light-colored with many windows and balconies. Some balconies have glass railings, while others are still open. The sky is clear and blue.	
	 A photograph of an interior room during a cleaning or renovation phase. Two workers wearing yellow hard hats and high-visibility vests are on the floor. One worker is kneeling and sweeping debris into a pile, while the other is standing nearby. The floor is covered with various pieces of trash, including plastic bags and paper. A large window on the right side of the room provides natural light.	

Tower 01

Other Work



Tower Name

Tower Photo

Work Done i.e.



Tower 02

Other Work



Tower Name

Tower Photo

Work Done i.e.



Tower 03

Other Work

