


Sikka Kimaantra Greens

Progress Report 29.04.25 to 05.05.25

	Photo	Work Done i.e.
NTA	 A photograph showing several construction workers in safety gear (hard hats and high-visibility vests) working on a dirt ground. They are laying out a rectangular concrete foundation for a tower. The workers are positioned around the perimeter of the foundation, which is made of concrete blocks and bricks. The background shows a white building and a corrugated metal structure.	Any Other Work
Tower Name	 A photograph showing a construction worker in a yellow hard hat and a high-visibility vest standing on a tiled floor. The floor is covered with a grid of rebar and some scattered bricks. The worker is looking down at the floor. In the background, there is a brick wall and a doorway. A sign in the foreground reads "Thanks for your Visit".	Work Done i.e.
Club		Any Other Work




Tower Name	Tower Photo	Work Done i.e.
Tower Name	Tower Photo	Work Done i.e.
		
Tower 01		Other Work



Tower Name

Tower Photo

Work Done i.e.



Tower 02

Other Work



Tower Name	Tower Photo	Work Done i.e.
Tower 03	 A photograph of a tall, modern apartment building with many balconies. The building is light-colored and has a repetitive architectural pattern. The sky is clear and blue. There are some palm trees and other vegetation at the base of the building.	Other Work

