

Sikka Kimaantra Greens

Progress Report 09.09.25 to 15.09.25

	Photo	Work Done i.e.
	 A photograph showing two construction workers on a rooftop platform. One worker is wearing an orange safety vest and a yellow hard hat, while the other is wearing a yellow safety vest and a yellow hard hat. They are standing on a concrete platform with several stacks of large, light-colored tiles in the foreground. The background shows a concrete wall and a blue container.	
NTA	 A photograph showing a construction worker wearing a yellow hard hat and an orange safety vest, standing on a metal scaffold. The worker is painting the ceiling of a balcony. A bucket of paint is visible on the scaffold. The background shows a view of a city and greenery.	Any Other Work



Tower Name

Tower Photo

Work Done i.e.



Club

Any Other Work

Tower Name	Tower Photo	Work Done i.e.
Tower 01		Other Work
		

Tower Name	Tower Photo	Work Done i.e.
------------	-------------	----------------



Tower 02

Other Work

