

Tower Name	Work Done i.e
<p>NON Tower</p>  A photograph showing several workers on a rooftop terrace. They are engaged in cleaning work, with some workers in orange and blue clothing. There are large white bags and a metal cage filled with debris. A modern glass building is visible in the background.	<p>Malwa Cleaning work</p>
<p>Retail Area</p>  A photograph of an indoor retail area. A worker is pushing a large wooden cart loaded with debris. The floor is light-colored and appears to be in the process of being cleaned or prepared. The area has concrete pillars and overhead lighting.	<p>Material Shifting work and malwa cleaning</p>
<p>Retail Area</p>  A photograph showing workers in a retail area constructing a brick partition wall. The workers are wearing yellow hard hats and are positioned around a brick wall under construction. Scaffolding and construction materials are visible.	<p>Shop Parition wall</p>

Atrium



Stone work at 23rd floor

Office tower



Steel shifting

Retail Area



Brick wall partition wall

**NON
Tower**



Glass railing work