

	Tower Name	Work Done i.e
<p>NON Tower</p>	 A photograph showing construction workers on a scaffolding structure inside a building. They are working on the walls of a fire fighting shaft, applying plaster. The area is filled with construction materials and equipment.	<p>Fire Fighting shaft plaster</p>
<p>Retail Area</p>	 A photograph showing the installation of a large, blue metal cooling tower structure. The structure is being positioned in an open area between buildings. Several workers are visible around the structure, and a crane is partially visible in the background.	<p>Cooling tower installation</p>
<p>Retail Area</p>	 A photograph showing workers performing FRP (Fiberglass Reinforced Plastic) work. They are working on a structure made of red metal frames. One worker is standing on a platform, while another is on the ground. A large white bag of material is visible in the foreground.	<p>FRP Work</p>

Atrium



Brick work

Office tower



Steel shifting

Retail Area



Brick wall partition wall

**NON
Tower**



**Italian Stone of
atrium**