

SIKKA MALL OF EXPRESSWAY

Progress Report for- 12/05/25 To 19/05/25

Mall Name	Mall Photo	Work Done i.e.
Mall of Expressway		Cantiliver work going on- 30 R/mtr
Mall Name	Mall Photo	Work Done i.e.
Mall of Expressway		RMC-
		Cantiliver steel binding work going on

Mall Name	Mall Photo	Work Done i.e.
<p>Mall of Expressway</p>		<p>2nd floor Dismantling work</p>

Mall Name	Mall Photo	Work Done i.e.
<p>Mall of Expressway</p>		<p>Work on the FRP for elevation side</p>

Mall Name	Mall Photo	Work Done ie.
<p>Mall of Expressway</p>		<p>1st floor cleaning work going on</p>
<p>Mall photo</p>	<p>Mall Photo</p>	<p>Work Done i.e.</p>
<p>Mall of Expressway</p>		<p>Column strengthening work going on – casting 20 cum</p>