







SIKKA MALL OF EXPRESSWAY

Progress Report for- 24/11/25 To 01/12/25

Mall Name	Mall Photo	Work Done i.e.
<p style="text-align: center;">Mall of Expressway</p>		2 nd floor partition wall brick work going on
Mall Name	Mall Photo	Work Done i.e.
<p style="text-align: center;">Mall of Expressway</p>		RMC-
		POP work in going on 2 nd floor

Mall Name	Mall Photo	Work Done i.e.
<p>Mall of Expressway</p>		<p>Wall dismantling work in going on</p>

Mall Name	Mall Photo	Work Done i.e.
<p>Mall of Expressway</p>		<p>Malva cleaning work in going on</p>

Mall Name	Mall Photo	Work Done ie.
<p>Mall of Expressway</p>		<p>Staircash ms railing work in going on</p>
<p>Mall photo</p>	<p>Mall Photo</p>	<p>Work Done i.e.</p>
<p>Mall of Expressway</p>		<p>Terrace kota stone work in going on</p>